


Document: 3

Former Robust UK Building, Sutherland Road, Longton, Stoke on Trent, ST3 1HZ

MFC / MDF Materials to be stored inside the Factory before processing



Perimeter of the Factory Boundary

Factory

External Location of the Cyclo Filter System

External Location of Enclosed Dust Collection Skip